

After Start Enrichment

- Ensure higher multipliers at very low temperatures to facilitate reliable cold starts.

Warm Conditions:

- Multipliers near or at 1.00 are suitable for warm engine starts to prevent over-fueling.

This table, like others, is essential for achieving reliable starts and maintaining consistent cranking performance across a range of temperatures.

